



Mobile Paint Mfg. Co., Inc.

MATERIAL SAFETY DATA SHEET

PRODUCT NAME: MO-SPRAY-CO™

PRODUCT CLASS:

PRODUCT CODE: 131-series (including product numbers: 131-9, 131-10, 131-11, 131-12, 131-17, 131-20, 131-26, 131-27, 131-28, 131-30, 131-31, 131-33, 131-37, 131-41, 131-42, 131-46, 131-49, 131-51, 131-53, 131-61, 131-63, 131-68, 131-71, 131-74, 131-78, 131-84)

HMIS RATINGS

H2 F3 R0

SECTION I - MANUFACTURER IDENTIFICATION

MANUFACTURER'S NAME: MOBILE PAINT MANUFACTURING CO., INC.

ADDRESS: P.O. BOX 717, THEODORE, AL 36582

DATE PREPARED: 01/11/07

PREPARER: J. Hoagland

EMERGENCY PHONE: 1-800-255-3924

(Chemtel 24 Hour Emergency)

INFORMATION PHONE: 251-443-6110

SECTION II - HAZARDOUS INGREDIENTS

| HAZARDOUS COMPONENT | CAS NUMBER | OSHA PEL | ACGIH TLV | VAPOR PRESS mmHg @ TEMP | SARA SEC. 313 * | WT. PERCENT |
|-------------------------------|-------------|-----------|-----------|-------------------------|-----------------|-------------|
| MINERAL SPIRITS | 8052-41-2 | 100 PPM | 100 PPM | 2.0@68 | | 0 - 2 |
| AROMATIC HYDROCARBON SOLVENT | 64742-95-6 | 100 PPM | 100 PPM | 2.0@68 | | 0-2 |
| XYLENE | 1330-20-7 | 100 PPM | 100 PPM | 6.0@68 | YES | 0 - 40 |
| ETHYLBENZENE | 100-41-4 | 100 PPM | 100 PPM | 75.0@68 | YES | 0 - 1 |
| TOLUENE | 108-88-3 | 100 PPM | 50 PPM | 22.0@68 | YES | 15 - 55 |
| ACETONE | 67-64-1 | | 750 PPM | 186.0@68 | | 0 - 15 |
| VM&P NAPHTHA | 64742-89-8 | 300 PPM | 300 PPM | 12.0@68 | | 0 - 20 |
| METHYL ETHYL KETONE | 78-93-3 | 200 PPM | 200 PPM | 70.0@68 | YES | 0 - 5 |
| LIQUEFIED PETROLEUM GAS | 68476-86-8 | 600 PPM | | 70@70 | | 30 |
| TITANIUM DIOXIDE | 13463-67-7 | 15 MG/M3 | 10 MG/M3 | N/A | | 0 - 10 |
| AMORPHOUS PRECIPITATED SILICA | 112926-00-8 | 20 MPPCF | 10 MG/M3 | N/A | | 0 - 2 |
| IRON OXIDE | 1309-37-1 | 5 MG/M3 | | N/A | | 0 - 10 |
| CARBON BLACK | 1333-86-4 | 3.5 MG/M3 | 3.5 MG/M3 | N/A | | 0 - 1 |
| ALUMINUM FLAKE | 7429-90-5 | 15 MG/M3 | 10 MG/M3 | N/A | YES | 0 - 5 |
| COPPER/ZINC POWDER | MIXTURE | UNKNOWN | 1 MG/M3 | N/A | YES | 0 - 10 |
| COPPER POWDER | 7440-50-8 | UNKNOWN | 1 MG/M3 | N/A | YES | 0 - 5 |
| CHROMIUM OXIDE | 1308-38-9 | 1 MG/M3 | 0.5 MG/M3 | N/A | YES | 0 - 2 |
| YELLOW IRON OXIDE | 51274-00-1 | 10 MG/M3 | 10 MG/M3 | N/A | | 0 - 5 |

* Ingredients marked YES are subject to the reporting requirements of the Superfund Amendments and Reauthorization Act (SARA) Section 313, 40 CFR 372.

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT: -13°F

VAPOR DENSITY: Heavier than air

VOC TOTAL (lb/gal): 4.36

VOC Less Water and Exempt Solvents (lb/gal): 4.90

APPEARANCE & ODOR: Typical paint solvent odor

SPECIFIC GRAVITY (H2O = 1): 0.8

EVAPORATION RATE: Faster than ether

SOLUBILITY IN WATER: Negligible

SECTION IV - FIRE & EXPLOSION HAZARD DATA

FLASH POINT: -4°F

METHOD USED:

UNUSUAL FIRE AND EXPLOSION HAZARDS:

Contents under pressure. At temperatures over 120 degrees F containers may vent, rupture or burst. Isolate from heat, electrical equipment, sparks and open flame. Application to hot surfaces requires special precautions. Full protective equipment which includes SCBA should be used. Protect personnel against bursting, rupturing or venting containers.

EXTINGUISHING MEDIA: FOAM, ALCOHOL FOAM, CO2, DRY CHEMICAL

FLAMMABLE LIMITS IN AIR BY VOLUME -

BLOWER: 0.8

UPPER: 9.5

SPECIAL FIRE FIGHTING PROCEDURES:

Water spray may be ineffective. If water is used, fog nozzles are preferable. Water may be used to cool closed containers to prevent pressure build-up and possible autoignition or explosion when exposed to extreme heat.

Mobile Paint Mfg. Co., Inc.

MATERIAL SAFETY DATA SHEET

Product Name: MO-SPRAY-CO™

Product Code: 131-series (including product numbers: 131-9, 131-10, 131-11, 131-12, 131-17, 131-20, 131-26, 131-27, 131-28, 131-30, 131-31, 131-33, 131-37, 131-41, 131-42, 131-46, 131-49, 131-51, 131-53, 131-61, 131-63, 131-68, 131-71, 131-74, 131-78, 131-84)

SECTION V – REACTIVITY DATA

| | |
|---|--|
| <p>STABILITY: Stable</p> <p>INCOMPATIBILITY (MATERIALS TO AVOID): Oxidizing materials</p> <p>HAZARDOUS DECOMPOSITION OR BYPRODUCTS: May produce hazardous fumes when heated to decomposition as in welding. Overexposure may cause a health hazard.</p> | <p>CONDITIONS TO AVOID: High Temperatures</p> <p>HAZARDOUS POLYMERIZATION: Will not occur.</p> |
|---|--|

SECTION VI – HEALTH HAZARD DATA

| | |
|---|--|
| <p>INHALATION HEALTH RISKS AND SYMPTOMS OF EXPOSURE: Anesthetic. Excessive inhalation can cause irritation of the respiratory tract, or acute nervous system depression characterized by headache, dizziness, staggering gait, confusion, unconsciousness, coma and even asphyxiation.</p> <p>SKIN & EYE CONTACT HEALTH RISKS AND SYMPTOMS OF EXPOSURE: Skin: Moderate irritation, defeating, dermatitis. May be a sensitizer in some individuals. Eyes: Severe irritation, redness, tearing, blurred vision. May be a sensitizer in some individuals</p> <p>SKIN ABSORPTION HEALTH RISKS & SYMPTOMS OF EXPOSURE: Liquid can be absorbed through the skin resulting in symptoms similar to the inhalation effects above.</p> <p>MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE: Exposure to petroleum solvents may aggravate preexisting dermatitis.</p> | <p>INGESTION HEALTH RISKS & SYMPTOMS OF EXPOSURE: Gastrointestinal irritation, nausea, vomiting and diarrhea. Aspiration into the lungs during ingestion or vomiting may cause mild to severe pulmonary injury and possibly even death.</p> <p>HEALTH HAZARDS (ACUTE AND CHRONIC); Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal.</p> <p>EMERGENCY AND FIRST AID PROCEDURES: Inhalation: Remove to fresh air. Administer oxygen if breathing is difficult. Restore breathing if necessary. Treat symptomatically. Consult a physician. Skin: Wash affected areas with soap and water. Remove and launder contaminated clothing. Consult a physician if needed. Eyes: Flush immediately with large amounts of water for at least 15 minutes. Take to a physician for medical treatment. Ingestion: Drink 1 or 2 glasses of water to dilute. Do not induce vomiting. Get medical help immediately.</p> |
|---|--|

SECTION VII – PRECAUTIONS FOR SAFE HANDLING AND USE

| | |
|--|--|
| <p>STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Remove all sources of ignition (flame, hot surfaces, and electrical, static or frictional sparks). Avoid breathing vapors. Ventilate area. Contain and remove with inert absorbent and non-sparking tools.</p> <p>PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Do not store above 120 F. Store large quantities only in buildings designed to comply with OSHA 1910.106. Keep closures tight and container upright to prevent leakage. Do not store or use near heat, sparks or flame. Do not place aerosol can in trash compactor. Do not puncture.</p> | <p>WASTE DISPOSAL METHOD: Dispose of in accordance with local, state and federal regulations. Incinerate in approved facility. Do not incinerate closed containers.</p> <p>OTHER PRECAUTIONS: Do not get in eyes. Avoid skin contact. Can cause allergic respiratory reaction. Can cause allergic skin reaction. Prevent prolonged or repeated breathing of vapors or spray mist. Avoid breathing of sanding dust. Wash contaminated clothing thoroughly. Wash skin thoroughly with soap and water after handling. Close container after each use. Do not handle until the manufacturer's safety precautions have been read and understood. Keep out of reach of children.</p> |
|--|--|

SECTION VIII – CONTROL MEASURES

| | |
|---|--|
| <p>RESPIRATORY PROTECTION: Use a NIOSH-approved respirator to prevent overexposure, when exposure exceeds occupational exposure limits (Section II). Use either an atmosphere-supplying respirator or an air-purifying respirator for organic vapors in compliance with 29 CFR 1910.134, with provision for mist removal if conditions so indicate.</p> <p>PROTECTIVE GLOVES: Recommended.</p> <p>OTHER PROTECTIVE CLOTHING OR EQUIPMENT: Use protective outerwear and prevent prolonged skin contact with contaminated clothing.</p> | <p>VENTILATION: All application areas should be ventilated in accordance to OSHA regulation 29 CFR 1910.94, 1910.107, 1910.108. Remove decomposition products formed during welding or flame cutting on surface coated with this product. If baking, vent fumes. These coatings may contain materials classified as nuisance particulates which may be present at hazardous levels only during sanding or abrading of the dried film. If no specific dusts are listed in Section II, the applicable limits for nuisance dusts are ACGIH TLV 10 mg/m³ (total dust), OSHA PEL 15 mg/m³ (total dust), 5 mg/m³ (respirable fraction).</p> <p>EYE PROTECTION: Safety eyewear including splashguards or side shields recommended.</p> <p>WORK/HYGIENIC PRACTICES: Avoid breathing vapors and contact with skin. Wash skin thoroughly before breaks and meals and at end of work period.</p> |
|---|--|

SECTION IX – DISCLAIMER

DISCLAIMER: The information provided in this MSDS has been obtained from sources believed to be accurate and reliable. It is furnished without warranty of any kind, express or implied. Recipients should determine that the information is current and suitable for the protection of the environment and the health and safety of your employees and users of this product.